Dependence of Surface Roughness on Depth of Cut for Aluminum Alloy AlCu4Mg1

Dusan Mital¹, Michal Hatala¹, Andrej Bernat¹, Andrej Czan³, Jaroslav Vybostek¹, Nicolae Ungreanu²

¹Faculty of Manufacturing technologies with a seat in Presov, Technical University of Kosice, Bayerova 1 street, 080 01 Presov, Slovakia, dusan.mital@tuke.sk, michal.hatala@tuke.sk, andrej.bernat@tuke.sk, jaroslav.vybostek@tuke.sk

²Universitatea de Nord din Baia Mare, Facultatea de Inginerie, Str. Dr. V. Babes 62A, RO-430083, Maramures, Romania, nicolae.ungureanu@ubm.ro

³Faculty of Mechanical Engineering at the University of Zilina, Veľký diel, 010 26 Zilina, Slovak Republic, andrej.czan@fstroj.uniza.sk


Presented article is focused on evaluating surface quality parameters Rz and Ra after turning made by various cutting conditions. Monitored parameters in experimental part were feed rate, cutting speed and depth of cut. Researching optimal cutting conditions, which sets often affect and increase productivity, quality and precision of manufactured products. Aim of the article is to increase quality of current state, what require long time testing and experiences. Article also presents individual comparing of two selected cutting plates in various cutting conditions, when in conclusion are clearly define results of experiment and requirement for practical using in industry.

Keywords: Lathe, Roughness, Surface Quality, Cutting Plates

1 Theoretical background and experimental part Open this template and delete all texts,

Experimental procedure was realized on CNC lathe Leadwell Twilight series T-5 (Fig. 1), which is intended for manufacturing shafts, flanges and other rotary parts. Control system of used CNC lathe is Fanuc 0i – TC with manual guide. LeadwellTwilight series T-5 is applicable fromsmall series to large series production. Cutting plates, DCGT 11 T3 02 - PM2, DCGT 11 T3 02 - PF2 with adequate holder was set as tool (Tab. 1.). Both of cutting plates has positive geometry [8], [6], [2], [10].

Tab. 1 Cutting plates used for experimental procedure



Tab. 2 Chemical composition of the material

LEADWOLL TO			
	□X ====		
			LEADWELL
Fig.	1 CNC lathe L	eadwell T-5	

Experimental part was realized with chosen material AlCu4Mg1 (EN 2024 T3) also called super Dural (Tab. 2.).. Super Dural is structural material used for manufacturing middle and high strained components, which are intended to long lifecycle for various loads or short time heat exposition. Main usage is in area of aircraft industry, railway industry and in automotive industry and in other industries, where technologies of machining are used [1], [3], [5], [9].

%	Si	Fe	Cu	Mn	Mg	Cr	Ni	Zn	Ti	Pb
min	-	-	3.8	0.3	1.2	-	-	-	-	-
max	0.5	0.4	4.9	0.9	1.8	0.1	-	0.25	0.1	-

Tab. 3 Mechanical properties of the material

1 tto. 5 meenta	near properties	of the materia	ı				
Rm [MPa]		Rp0.2 [MPa]		A [0/]	A50[%]	Hardness [HB]	
min	max	min	max	A [%]	A30[70]	Hardness [HB]	
420	-	270	-	10	8	120	

2 Dependence of surface quality on depth of cut

Experiment was aimed to observe and evaluate dependence of surface roughness on depth of cut.

Cutting plates used for experiment was with 0. 4 mm corner radius. Cutting plates are intended to manufacture

aluminum alloys and dispose with two types of chip former. Experimental parts were realized without additional lubricating or cooling [4], [7], [6], [11].

Cutting conditions for experimental procedure were set on values as follows:

• cutting speed vc= 300m.min-1

- feed rate per revolution f= 0.8 mm
- depth of cut- ap=0.5 mm
 - ap=1mm,
 - ap=2 mm,
 - ap=3 mm.

Cutting plate used in turning process was used in continual cut process with length 20 mm for each plate individually.

Results and analysis of experiment

Values of surface roughness Ra and Rz obtained from roughness meter Mitutoyo SJ-400 (Fig. 2.) are in table below (Tab. 4).

Lowest value of surface roughness was achieved with

cutting plate provided with chip former PF2 and at depth of cut ap=2 mm specifically Ra= $0.93 \mu m$. Oppositely the same plate at depth of cut 3 mm create surface with roughness parameter Ra on values $4.78 \mu m$. Maximum height of surface roughness Rz was obtained with cutting plate with chip formation PM2, where was obtained lower values with increasing depth of cut (Tab.4.).



Fig. 2 Measuring experimental parts using Mitutoyo SJ-400

Tab. 4 Measured values of Ra and Rz

	Ra [μm]	Rz [μm]			
Depth of cut		Cutting plate				
ap [mm]	DCGT 11 T3 02 - PM2	DCGT 11 T3 02 - PF2	DCGT 11 T3 02 - PM2	DCGT 11 T3 02 - PF2		
0.5	1.12	1.07	4.4	4.7		
1	1.17	1.04	4.3	4.4		
2	1.09	0.93	4.3	5.5		
3	1.03	4.78	4.2	29.8		

Graphical dependence (Fig. 3.) of surface roughness on depth of cut is basis for the claim, that cutting plate DCGT 11 T3 02 - PM2 with increasing depth of cut the surface roughness is continually decrease except one occasion in depth of cut ap = 1 mm was surface roughness measured was more about $0.05\mu m$ than at depth of cut ap

= 0.5 mm and more about 0.07 μ mat depth of cut ap= 2 mm. Cutting plate, which is designed for finishing operation, obtained at depth of cut ap = 2 lower values with increasing depth of cut in comparison to cutting plate with chip formation PM2.

Graphical dependence of surface roughness Ra on depth of




Fig. 3 Dependence of surface roughness Ra on depth of cut ap

Comparing previous (Fig. 4) occasion with graphical dependence below constructed by measured values of maximal surface roughness of machined surface with cutting tool PF2 obtain higher quality of the monitored surface. Values of maximal height of surface roughness

Rz obtained with cutting plate with chip former PF2 minimally decrease to depth of cut 2 mm on values $4.7\mu m$ and depth of cut 2 mm can be consider as boundary condition of qualitative indicator (in this case surface roughness Rz).

Graphical dependence of surface roughness Rz on depth of cut ap




Fig. 4 Dependence of surface roughness Rz on depth of cut a_p




Fig. 5 Setting of standard cutting conditions

Differences of qualitative character are shown in table follows, where is obvious, that surface roughness at depth of cut ap = 3 mm is diverse, where can be state, that shape of chip former directly influence surface quality and also possibility of cutting condition sets.

Differences in surface quality can be occurred by experimental conditions (without cooling and lubrication), and also of set of cutting parameters, where cutting plate with chip former PF2 was near to boundary prescribed by producer of plate (Fig. 5).

- Following picture (Fig.6.) shows surface machined with cutting plate DCGT 11 T3 02 PF2 and cutting conditions as follows:
- Cutting speedvc=300 m.min-1
- Feed ratef = 0.8 mm/rev
- Depth of cut ap= 3 mm



Fig. 6 Surface machined with DCGT 11 T3 02 - PF2 at depth of cut 3 mm



Fig. 7 Surface machined with DCGT 11 T3 02 - PF2 at depth of cut 3 mm

With listed cutting conditions were obtained values of surface roughness parameters $Ra=4.78~\mu m$ and $Rz=29.8~\mu m$. Surface of experimental part is visually scratchy and very rough. Lower surface quality was caused because chip former was not able to remove chip from place

April 2018, Vol. 18, No. 2 MANUFACTURING TECHNOLOGY ISSN 1213-2489

of cutting.

On the other side, as is shown on picture below (Fig. 7.), with same shape of cutting plate equipped with different chip former (DCGT 11 T3 02 - PM2) is surface quality non comparable better. Machined surface is smooth, without visual tracks caused by tool. Surface roughness parameters obtained in this case were $Ra = 1.03 \mu m$ and $Rz = 4.2 \mu m$. Experimental sample was machined with cutting conditions which were same as in previous case:

- Cutting speed vc=300 m.min⁻¹
- Feed rate f = 0.8 mm/rev
- Depth of cut ap= 3 mm

Required prescribed surface roughness was obtained for both plates except of cutting plate DCGT 11 T3 02-PF2 at depth of cut ap = 3 mm.

Cutting plate DCGT 11 T3 02-PF2 at depth of cut 0.5 – 1 mm form short helical chip and at higher depth of cut was chip formed into broken chips, what is appropriate and desirable for chip management. Chip management contain unwritten rule, that broken chip point on higher surface quality.

Cutting plate DCGT 11 T3 02-PM2 form heliacal chip, which increasing character with value of set depth of cut and was broken in periodical interval. Chip with longest character was obtained in machining process with depth of cut 2mm, what could occur to tangle of chip on workpiece or tool, what can negatively affect durability of tool, machine and also quality of machined surface (Tab.5.)

3 Conclusion

Depth of cut is one of most significant cutting conditions which can affect quality of machined surface and on the other side manufacturing time. This experiment was focused on determining maximal depth of cut at which is surface quality on acceptable level. As shown in the results most of cutting plates are able to maintain balanced surface quality in whole interval prescribed by producer of plates

Tab. 5 Shape of chips

Cutting	Shape of a chip Depth of cut ap [mm]						
plate	0,5	1	2	3			
DCGT 11 T3 02-PM2							
DCGT 11 T3 02-PF2							

Acknowledgement

This article was supported by project VEGA 1/0682/17.

References

- [1] J. ZAJAC, D. MITAL, P. MICHALIK (2014). Verification of process fluids in mass production,in: J. Kundrat, Z. Maros (Eds.), *Precision Machining VII Book series: Key Engineering Materials*, 2014, pp. 554-559.
- [2] I. VOJTKO, V. SIMKULET, P. BARON, et al. (2014). Microstructural Characteristics Investigation of the Chip-Making Process after Machining,in: S. Fabian, T. Krenicky (Eds.), Operation and Diagnostics of Machines and Production Systems Operational States II book series: Applied Mechanics and Materials, 2014, pp. 344-350.
- [3] R. CEP, A. JANASEK, J. PETRU, et al. (2014). Surface Roughness after Machining and Influence of Feed Rate on Process, in: *J. Kundrat, Z. Maros (Eds.), Precision Machining VII Book Series: Key Engineering Materials*, 2014, pp. 341-347.
- [4] BOŽEK P, NIKITIN Y, BEZÁK P, FEDORKO G, FABIAN M. (2015). Increasing the production system productivity using inertial navigation in:. In *MANUFACTURING TECHNOLOGY*. 2015. Vol. 15, No. 3 s. 396 403. ISSN 1213–2489
- [5] J. ZIVCAK, M. PETRIK, R. HUDAK, et al. (2009). Embedded Tensile Strenght Test Machine FM1000-An Upgrade of Measurement and Control, in: Z. Gosiewski, Z. Kulesza (Eds.), Mechatronic systems and materials III., Book Series: Solid State Phenomena, 2009, pp. 657-662.
- [6] J. ZAJAC, D. MITAL, S. RADCHENKO, et al. (2014). Short-term Testing of Cutting Materials Using the Method of Interrupted Cut, in: S. Fabian, T. Krenicky (Eds.), Operation and Diagnostics of Machines and Production Systems Operational States II book series: Applied Mechanics and Materials, 2014, pp. 236-243.
- [7] J. KOVAL. Optimalization of Cutting Conditions of Turning (*diploma thesis*), 2015.
- [8] PETRU, J. SCHIFFNER, J. ZLAMAL, T. SADILEK, M. STANCEKOVA, D. (2015). Investigations of Cutting Tool Wear While MachiningInconel 718. In MANUFACTURING TECHNOLOGY. 2015. Vol. 15, No. 3 s. 396 403. ISSN 1213–2489
- [9] S. F. KRAR, A. R. GILL, A. R. SMID (2011). Technology of Machine Tools, 7th ed., McGraw-Hill, New York, 2011.
- [10] I. MUKHERJEE, P. K. RAY (2006). A review of Optimization Techniques in *Metal Cutting Processes, Computer and Indrustrial engineering.* 50 (2006) 15-34.
- [11] KOURIL K., CEP R., JANASEK A., KRIZ A., STANCEKOVA D. (2014). Surface Integrity at Reaming Operation by MT3 Head. In: *Manufacturing technology*, Vol. 14, No. 2, pp. 193 199, ISSN 1213-2489

10.21062/ujep/92.2018/a/1213-2489/MT/18/2/285

Copyright © 2018. Published by Manufacturing Technology. All rights reserved.